

DESCRIÇÃO DA OBRA	DIMENSÕES BÁSICAS		
	EXT. (m)	ALT. (m)	ÁREA (m2)
Cortina Ancorada (Estaqueada) + Guarda Corpo	14,0	6,0	84,0
Biomanta Vegetal	15,0	Var.	150,0
Reconstituição de Passeio	15,0	-	25,0
Muro em Ciclopico	10,0	1,7	17,0

A photograph showing a severe landslide on a road in Japan. The road surface is partially collapsed, revealing a deep, exposed soil pit. Numerous tree roots are visible, having been pulled out of the ground by the erosion. A white car is parked on the road above the landslide. Orange safety netting is strung across the bottom of the pit, and a yellow and black striped warning sign is visible on the right side of the road. The background shows a steep, forested hillside under a cloudy sky.

Diagrama de uma parede com quatro tipos de revestimento:

- CORTINA ANCORADA**: Representado por uma barra sólida preta.
- BIOMANTA VEGETAL**: Representado por uma barra com diagonais paralelas.
- RECOMPOSIÇÃO DE PASSEIO**: Representado por uma barra com um padrão de pequenos retângulos.
- MURO EM CICLOPICO**: Representado por uma barra com um padrão de pedras irregulares.

[illegible]